



**Intersil Corporation
P.O. Box 883
2401 Palm Bay Road
Palm Bay, Florida 32905**

(321) 724-7000

March 30, 2001

To: Our Valued Customers

Attention: Procurement Manager

Subject: **PLC#01001 Report 1 - Quarterly Product Withdrawal Notice –
Standard Products**

Intersil Corporation is pleased to have been your supplier for the products identified in the attached list and is sorry to notify you that they will no longer be available. Only specific products listed are affected.

Due to specific reasons, cited in the product list, we will no longer be manufacturing these products.

Intersil proposes you give consideration to a final life-of-type procurement for these parts. We recognize that you will need some time to analyze your requirements. Therefore, we will accept orders on these products until September 23, 2001 with shipments to be scheduled no later than March 24, 2002.

In this notice, we have listed possible second sources/substitutes for these products, in cases where we have been able to identify them. If you need assistance or further information, please contact your Intersil Regional Sales Office or the individual contact cited in the list.

If you are considering a redesign, and require assistance, please call our Intersil Hot Line, 1-888-468-3774, for our Applications Department.

Parts List Hyperlink to Excel Spreadsheet

..\Parts List\PLC01001_Std06Q101.xls

Customer Relations Dept
Intersil Corporation

PLC#01001
Q1 CY'01
Report 1



**Intersil Corporation
P.O. Box 883
2401 Palm Bay Road
Palm Bay, Florida 32905**

(321) 724-7000

March 30, 2001

To: Our Valued Customers

Attention: Procurement Manager

Subject: **PLC#01001 – Report 2 - Quarterly Product Withdrawal Notice
Custom /Proprietary Products**

Intersil Corporation is pleased to have been your supplier for the products identified in the attached list and is sorry to notify you that they will no longer be available. Only specific products listed are affected.

Due to specific reasons, cited in the product list, we will no longer be manufacturing these products.

Intersil proposes you give consideration to a final life-of-type procurement for these parts. We recognize that you will need some time to analyze your requirements. Therefore, we will accept orders on these products until March 24, 2002 with shipments to be scheduled no later than September 23, 2002.

In this notice, we have listed possible second sources/substitutes for these products, in cases where we have been able to identify them. If you need assistance or further information, please contact your Intersil Regional Sales Office or the individual cited in the list.

If you are considering a redesign, and require assistance, please call our Intersil Hot Line 1-888-468-3774, for our Applications Department.

Parts List Hyperlink to Excel Spreadsheet

[..\Parts List\PLC01001_Cus12Q101.xls](#)

Customer Relations Dept
Intersil Corporation

PLC#01001
Q1, CY01
Report 2



**Intersil Corporation
P.O. Box 883
2401 Palm Bay Road
Palm Bay, Florida 32905**

(321) 724-7000

March 30, 2001

To: Our Valued Customers

Attention: Procurement Manager

**Subject: PLC#01001 Report 3 – Quarterly Product Withdrawal Notice
Product Re-Instatement and Accelerated, Withdrawals**

Intersil Corporation is pleased to have been your supplier for the products identified in the attached list.

This notice lists parts being withdrawn to a cycle time which differs from the six and twelve month notice intervals normally provided for product withdrawals. Please note that dates of withdrawal and obsolescence vary by product.

We have also provided a list of products for which notice, withdrawal and obsolescence dates may have changed since you were notified of their upcoming withdrawals and a list of products which have been re-instated during this time period. Please review the lists and make adjustments as necessary in your database. Each list provides appropriate dates and other information.

If you need assistance or further information, please contact your Intersil Regional Sales Office .

If you are considering a redesign, and require assistance, please call our Intersil Hot Line, 1-888-468-3774, for our Applications Department.

Parts List Hyperlink to Excel Spreadsheet

[..\Parts List\PLC01001_AccQ101.xls](#)

Customer Relations Dept
Intersil Corporation

PLC#01001
Q1 CY'01
Report 3

**Intersil Corporation Q1, CY2001 Quarterly Withdrawal Notice
PLC01001
Standard Product Parts List**

Pre-Notification : March 24, 2001
Withdrawal Date : September 23, 2001
Obsolete Date : March 24, 2002

Intersil Part No#	Customer Part Number	CCNL	Withdrawal Reason	Second Source	Replacement Part	Product Line Manager	Phone	Product Class	PLC
CA0158M		001	ELIMINATION OF MASK SERIES	NONE	NONE	JOHNSON	(321) 724-7138	S	A4G
CA0258M		001	ELIMINATION OF MASK SERIES	NONE	NONE	JOHNSON	(321) 724-7138	S	A4G
CD4027BHSR	5962R9662901V9A	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1A
CD4028BHSR	5962R9663001V9A	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1A
CD4077BDMSR	5962R9661102VCC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1A
DG300ABK		001	NOT ALIGNED WITH BUSINESS OBJECTIVE	NONE	NONE	JOHNSON	(321) 724-7138	S	B6A
HA1-5114/883		050	NOT ALIGNED WITH BUSINESS OBJECTIVE	NONE	NONE	SHAFFER	(321) 724-7651	M	V1H
HA4-5114/883		050	NOT ALIGNED WITH BUSINESS OBJECTIVE	NONE	NONE	SHAFFER	(321) 724-7651	M	V1H
HA7-5222/883		050	NOT ALIGNED WITH BUSINESS OBJECTIVE	NONE	NONE	SHAFFER	(321) 724-7651	M	V1H
HIP6018EVAL1		001	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	LAKKAS	(919) 405-3616	S	D3C
HIP6019EVAL1		001	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	LAKKAS	(919) 405-3616	S	D3C
HI5714/4CB-T		001	ADMINISTRATIVE WITHDRAWAL	ISIL	HI5714/4CB	TUCKER	(321) 729-4665	S	B1D
HMU17JC-35		001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	HMU17JC-45	OLIVER	(321) 729-4862	S	A7D
HSP48901JC-20		001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	HSP48901JC-30	OLIVER	(321) 729-4862	S	A7C
HSP48908JC-32		001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	HSP48908JC-20	OLIVER	(321) 729-4862	S	A7C
HSP9501JC-2596		001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	HSP9501JC-25	OLIVER	(321) 729-4862	S	A7E
HS7B-2620RH-QS9000	5962D9568801VPC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HS7B-2620RH-Q	MARSHALL	(321) 729-5690	M	M4B
ICL7662CTV		001	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	ICL7662MTV	BOGUT	(321) 729-4911	S	A3J
164034-001-0D			OBSOLETE TECHNOLOGY	ISIL	NONE	ABRAMOWITZ	(408) 891-3290	S	A1T

Intersil Corporation Q1, CY2001 Quarterly Withdrawal Notice
PLC01001
Custom/Proprietary Product Parts List

Pre-Notification : March 24, 2001
Withdrawal Date : March 24, 2002
Obsolete : September 23, 2002

Intersil Part No#	Customer Part Number	CCNL	Withdrawal Reason	Second Source	Replacement part	PL Manager/Contact	Phone	Product Class	PLC
CA3338MS2075	407011329	002	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	CA3338M	TUCKER	(321) 729-4665	C	B2D
CD40109BHSR	5962R9664501V9A	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1A
CD4027BDMSR	5962R9662901VEC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1A
CD4028BDNSR	5962R9663002VEC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1A
CD4047BKMSRS9000	5962R9663501VXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	CD4047BKMSR	TIMMERMAN	(321) 724-7430	T	M1A
CD4050BHSR	5962R9663701V9A	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1A
CD4050BKMSRS9000	5962R9663701VXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	CD4050BKMSR	TIMMERMAN	(321) 724-7430	T	M1A
CD4051BHSR	5962R9665101V9A	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1A
CD4066BHSR	5962R9665201V9A	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1A
CD4078BDMSR	5962R9663801VCC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1A
CP80C86-2S2064	407849827	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CP80C86-2	TRIEBELL	(407) 729-4574	C	K11
CP82C37A-5S2064	407827302	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CP82C37A-5	TRIEBELL	(407) 729-4574	C	K74
CP82C54S2485	A0326475	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CP82C54	TRIEBELL	(407) 729-4574	C	K74
CP82C55AS2580	405051699LAS	001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CP82C55A	TRIEBELL	(407) 729-4574	C	K74
CP82C59AS2485	A0326943	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CP82C59A	TRIEBELL	(407) 729-4574	C	K74
CP82C59AS2580	406974139LAS	001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CP82C59A	TRIEBELL	(407) 729-4574	C	K74
CP82C84AS2485	A0326944	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CP82C84A	TRIEBELL	(407) 729-4574	C	K74
CP82C88S2485	A0327074	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CP82C88	TRIEBELL	(407) 729-4574	C	K74
CS82C54-1096S2074	407935535	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CS82C54-1096	TRIEBELL	(407) 729-4574	C	K74
CS82C54-1096S2075	406848358	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CS82C54-1096	TRIEBELL	(407) 729-4574	C	K74
CS82C55A96S2075	406612846	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CS82C55A96	TRIEBELL	(407) 729-4574	C	K74
CS82C55A96S2485	A0336544	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CS82C55A96	TRIEBELL	(407) 729-4574	C	K74
CS82C59A96S2075	408398543	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	CS82C59A96	TRIEBELL	(407) 729-4574	C	K74
HAA0-51045R4194	8655576-004	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	NONE	ROBINSON	(407) 724-7600	P	MBA
HAA0-51405R4347	A584C384-101	050	NEW REPLACEMENT PART	ISIL	HAA0-51405R4649	ROBINSON	(407) 724-7600	P	MBA
HAA9-39531R4532	1343901-3	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	JONES	(407) 729-5227	P	MBA
HAA9-50062R4533	1343902-3	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	JONES	(407) 729-5227	P	MBA

Intersil Corporation Q1, CY2001 Quarterly Withdrawal Notice
PLC01001
Custom/Proprietary Product Parts List

Pre-Notification : March 24, 2001
Withdrawal Date : March 24, 2002
Obsolete : September 23, 2002

Intersil Part No#	Customer Part Number	CCNL	Withdrawal Reason	Second Source	Replacement part	PL Manager/Contact	Phone	Product Class	PLC
HAA9-50151R4531	1342827-3	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	JONES	(407) 729-5227	P	MBA
HAA9P-51177R3491		001	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HAA9P-51177R4736	JONES	(407) 729-5227	C	42D
HCS125KMSR	5962R9580301VXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCS151DMSR	5962R9572801VEC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCS244DTR	5962R9573101TRC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCS244KTR	5962R9573101TXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCS573DMSR	5962R9579401VRC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCTS153DMSR	5962R9575401VEC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCTS157HMSR	5962R9575501V9A	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCTS161ADMSR	5962R9577001VEC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCTS193DMSR	5962R9575701VEC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCTS193HMSR	5962R9575701V9A	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCTS20DMSR	5962R9573301VCC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCTS365HMSR	5962R9577501V9A	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCTS4002DMSR	5962R9576001VCC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HCTS4002KMSR	5962R9576001VXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	TIMMERMAN	(321) 724-7430	M	M1B
HC5503TCP		001	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HC5503TCB	LUDEMAN	(407) 724-7291	S	G1A
HC5547CMS2584		001	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HC5503TCB	LUDEMAN	(407) 724-7291	C	G1A
HC5547CPS2553		001	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HC5503TCB	LUDEMAN	(407) 724-7291	C	G1A
HC9P5504B-5X96S2570		002	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HC9P5504B-5X96	LUDEMAN	(407) 724-7291	C	G1A
HC9P5509B3999-003		001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	HC9P5509B-5	LUDEMAN	(407) 724-7291	C	G2A
HDV-52597	DPN-D355AA-B01	001	ADMINISTRATIVE WITHDRAWAL	NONE	NONE	LUDEMAN	(407) 724-7291	C	G9A
HFA3424IB		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3424IB1K		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3424IB96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3524IA		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3524IA96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y

Intersil Corporation Q1, CY2001 Quarterly Withdrawal Notice
PLC01001
Custom/Proprietary Product Parts List

Pre-Notification : March 24, 2001
Withdrawal Date : March 24, 2002
Obsolete : September 23, 2002

Intersil Part No#	Customer Part Number	CCNL	Withdrawal Reason	Second Source	Replacement part	PL Manager/Contact	Phone	Product Class	PLC
HFA3524IA96S2594		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1Y
HFA3624IA		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3624IA1K		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3624IA96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3624IA96S5001	9902C	001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1Y
HFA3663IA		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3663IAX6176		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1W
HFA3663IA96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3665IA		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3665IA96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3724IN		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3724INS2539		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1Y
HFA3724IN96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3724IN96S5001	9900C	001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1W
HFA3725R3417		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1W
HFA3726IN		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3726INR4863		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1Y
HFA3726IN96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3726IN96R4863		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1Y
HFA3726IN96R4863-CIS	15-5344-01	001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1Y
HFA3726IN96S2602	50-23130-143	001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1Y
HFA3761IN		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3761IN96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3763IN		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3763IN96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3765IA		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3765IA96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W

Intersil Corporation Q1, CY2001 Quarterly Withdrawal Notice
PLC01001
Custom/Proprietary Product Parts List

Pre-Notification : March 24, 2001
Withdrawal Date : March 24, 2002
Obsolete : September 23, 2002

Intersil Part No#	Customer Part Number	CCNL	Withdrawal Reason	Second Source	Replacement part	PL Manager/Contact	Phone	Product Class	PLC
HFA3766IN		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3767IA		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3767IA96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3824AIV		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3824AIVS5001	39802C	001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1Y
HFA3824AIV96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3824AIV96S2594		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1Y
HFA3860AIV		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3860AIV96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3860BIV		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3860BIV96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3860BIV96S2594		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1Y
HFA3860BIV96S2602	50-23130-142	001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1Y
HFA3860IV96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3861AIN		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Z
HFA3861AIN96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Z
HFA3925IA		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3925IA1K		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3925IA96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1Y
HFA3926IA		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	S	A1W
HFA3926IA96		001	OBSOLETE TECHNOLOGY	NONE	NONE	LAING	(321)724-7236	C	A1W
HIP6004CB-TS2490	0798703	040	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	LAKKAS	(919)405-3616	C	D3C
HIP6018CBS2557		001	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	LAKKAS	(919)405-3616	C	D3C
HIP6500CB-TS2490	IBMYASU	040	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	LAKKAS	(919)405-3616	C	D3C
HI1171JCB-TS2485	A0638039	002	NO ORDER ACTIVITY LAST 18 MONTHS	SONY	HI1171JCB-T	TUCKER	(321) 729-4665	C	BRC
HI3197JCQ		001	NO ORDER ACTIVITY LAST 18 MONTHS	SONY		TUCKER	(321) 729-4665	S	BRC
HI5721BIB-TS2490	09J5063	002	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HI5721BIB-T	TUCKER	(321) 729-4665	C	B1E

Intersil Corporation Q1, CY2001 Quarterly Withdrawal Notice
PLC01001
Custom/Proprietary Product Parts List

Pre-Notification : March 24, 2001
Withdrawal Date : March 24, 2002
Obsolete : September 23, 2002

Intersil Part No#	Customer Part Number	CCNL	Withdrawal Reason	Second Source	Replacement part	PL Manager/Contact	Phone	Product Class	PLC
HMP8156ACNS2525		001	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HMP8156ACN	TUCKER	(321) 729-4665	C	50A
HSP43220VC-33		001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	HSP43220JC-33	OLIVER	(407) 729-4862	S	A7B
HSP45256JC-25		001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ALTERA O	FPGA	OLIVER	(407) 729-4862	S	A7C
HSP45256JC-33		001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ALTERA O	FPGA	OLIVER	(407) 729-4862	S	A7C
HSP50306SC-25		001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	HSP50306SC-27	OLIVER	(407) 729-4862	S	A7H
HSP50306SC-2796		001	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	HSP50306SC-27	OLIVER	(407) 729-4862	S	A7H
HS0-9008RH-Q	HS0-9008RH-Q	050	DISCONTINUED MANUFACTURING PROCESS	NONE	NONE	MARSHALL	(407) 729-5690	T	M4D
HS1-139RH-QS9000	5962F9861301VCC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HS1-139RH-Q	MARSHALL	(407) 729-5690	T	M4F
HS1-508BRH-QS9000	5962F9674202VEC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HS1-508BRH-Q	MARSHALL	(407) 729-5690	M	M4A
HS1-9008RH-Q	5962F9669601VXC	050	DISCONTINUED MANUFACTURING PROCESS	NONE	NONE	MARSHALL	(407) 729-5690	M	M4D
HS1-9008RH/PROTO	HS1-9008RH/PROTO	050	DISCONTINUED MANUFACTURING PROCESS	NONE	NONE	MARSHALL	(407) 729-5690	N	M4D
HS8-RTX2010RH-Q	5962F9563501VXC	050	PACKAGE NOT AVAILABLE FROM SUPPLIER	ISIL	HS9-RTX2010RH-Q	MARSHALL	(407) 729-5690	M	M2D
HS8-RTX2010RH-8	5962F9563501QXC	050	PACKAGE NOT AVAILABLE FROM SUPPLIER	ISIL	HS9-RTX2010RH-8	MARSHALL	(407) 729-5690	M	M2D
HS8-RTX2010RH/PROTO	HS8-RTX2010RH/PROTO	050	PACKAGE NOT AVAILABLE FROM SUPPLIER	ISIL	HS9-RTX2010RH/PROTO	MARSHALL	(407) 729-5690	N	M2D
HS9-OP470ARH-QS9000	5962R9853301VXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HS9-OP470ARH-Q	MARSHALL	(407) 729-5690	T	M4B
HS9-139RH-QS9000	5962F9861301VXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HS9-139RH-Q	MARSHALL	(407) 729-5690	T	M4F
HS9-508BRH-8S9000	5962F9674202QXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HS9-508BRH-8	MARSHALL	(407) 729-5690	M	M4A
HS9-565ARH-QS9000	5962R9675501VXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HS9-565ARH-Q	MARSHALL	(407) 729-5690	N	M4D
HS9-6617RH-8S9000	5962R9570801QXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HS9-6617RH-Q	MARSHALL	(407) 729-5690	N	M3D
HS9-82C37ARH-Q	5962R9582101VXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HS1-82C37ARH-Q	MARSHALL	(407) 729-5690	M	M2B
HS9-82C37ARH-8	5962R9582101QXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HS1-82C37ARH-8	MARSHALL	(407) 729-5690	M	M2B
HS9-9008RH-Q	5962F9669601VYC	050	DISCONTINUED MANUFACTURING PROCESS	NONE	NONE	MARSHALL	(407) 729-5690	M	M4D
HS9-9008RH/PROTO	HS9-9008RH/PROTO	050	DISCONTINUED MANUFACTURING PROCESS	NONE	NONE	MARSHALL	(407) 729-5690	N	M4D
HS9A-1840ARH-QR4850	HS9A-1840ARH-QR4850	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	MARSHALL	(407) 729-5690	P	M4A
HS9S-117RH-8S9000	5962F9954701QXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	HS9S-117RH-Q	MARSHALL	(407) 729-5690	N	M4F
IS1-2981RH-QS9000	5962R0052001VVC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	IS1-2981RH-Q	MARSHALL	(407) 729-5690	M	M4F
IS2-1009RH-QS9000	5962F0052301VXC	050	NO ORDER ACTIVITY LAST 18 MONTHS	ISIL	IS2-1009RH-Q	MARSHALL	(407) 729-5690	T	M4F

**Intersil Corporation Q1, CY2001 Quarterly Withdrawal Notice
PLC01001
Custom/Proprietary Product Parts List**

Pre-Notification : March 24, 2001
Withdrawal Date : March 24, 2002
Obsolete : September 23, 2002

Intersil Part No#	Customer Part Number	CCNL	Withdrawal Reason	Second Source	Replacement part	PL Manager/Contact	Phone	Product Class	PLC
IS82C55A96S2485	A0346300	002	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	IS82C55A96	TRIEBELL	(407) 729-4574	C	K14
MD82C88/7	5962-9672701VRC	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	MARSHALL	(407) 729-5690	M	M2B
TA12004R0444	3253801	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	ROBINSON	(407) 724-7600	P	MBA
TA12005R0445	3253795	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	ROBINSON	(407) 724-7600	P	MBA
TA12138R0446	3253799	050	NO ORDER ACTIVITY LAST 18 MONTHS	NONE	NONE	ROBINSON	(407) 724-7600	P	MBA
100898	1947697A1	001	NOT ALIGNED WITH BUSINESS OBJECTIVE	NONE	NONE	JONES	(407) 729-5227	C	C15
10370225-A1			NEW REPLACEMENT PART	ISIL	10370225-A2	ABRA,PWOTZ		S	A1U
10410208-B2			NEW REPLACEMENT PART	ISIL	10410208-B3	ABRA,PWOTZ		S	A1T
164034-021-0D			OBSOLETE TECHNOLOGY	ISIL	NONE	ABRA,PWOTZ		S	A1T
164034-051-0D			OBSOLETE TECHNOLOGY	ISIL	NONE	ABRA,PWOTZ		S	A1T
5962-8954001LA		050	NOT ALIGNED WITH BUSINESS OBJECTIVE	ISIL	HM6-6617/883	TRIEBELL	(407) 729-4574	M	WB5
5962-8965603CA		050	NOT ALIGNED WITH BUSINESS OBJECTIVE	NONE	NONE	SHAFER	(321) 724-7651	M	V1L
60011109			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60011110			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60011143			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60011154			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60011211			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60011222			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1S
60011233			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60011244			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1S
60011277			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1S
60011288			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60011299			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1S
60012100			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60012111			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60012302			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60012504			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T

Intersil Corporation Q1, CY2001 Quarterly Withdrawal Notice
 PLC01001
 Custom/Proprietary Product Parts List

Pre-Notification : March 24, 2001
 Withdrawal Date : March 24, 2002
 Obsolete : September 23, 2002

Intersil Part No#	Customer Part Number	CCNL	Withdrawal Reason	Second Source	Replacement part	PL Manager/Contact	Phone	Product Class	PLC
60012649-A			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1S
60013101			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60013202			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60013213			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60021201-B			NEW REPLACEMENT PART	ISIL	60021201-C	ABRA,PWOTZ		S	A1T
60040112-A			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1S
60040235-A			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1S
60040257-A			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1S
60045207-A			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1T
60045353-A			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1U
60045364-A			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1U
60045375-A			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1U
70040102			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1S
70040113			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1S
70040124			OBSOLETE TECHNOLOGY	NONE	NONE	ABRA,PWOTZ		S	A1S

Report 3**Distribution Date : March 30, 2001****Intersil Corporation Q1, CY2001 Quarterly Withdrawal Notice****PCN#01001****Sheet 2 of 3****Accelerated Products**

Date	Part Type	WD	OBS	Pre-Not	Reason	Replacement Part	Contact	Contact Phone No.
01-Mar-01	CA3054W	30-Mar-01	27-Apr-01	30-Mar-01	Keep systems active through Lot build process	None	K.Shafer	(321) 724-7651
12-Mar-01	CA3039	30-Mar-01	29-Jun-01	20-Mar-01	Discontinued Manufacturing Process	None	K.Shafer	(321) 724-7651
12-Mar-01	CA3039M	30-Mar-01	29-Jun-01	20-Mar-01	Discontinued Manufacturing Process	None	K.Shafer	(321) 724-7651
16-Mar-01	HC4P5504BB4017-103	30-Mar-01	27-Apr-01	30-Mar-01	Inventory Sale	None	C.Ludeman	(321) 724-7291
28-Mar-01	ISL83385IA	30-Mar-01	30-Mar-01	20-Mar-01	Not aligned with business objectives	ISL83385E1A	J.Alcorn	(321) 724-7046
28-Mar-01	ISL83385IA-T	30-Mar-01	30-Mar-01	20-Mar-01	Not aligned with business objectives	ISL83385E1A-T	J.Alcorn	(321) 724-7046
28-Mar-01	ISL83385IB	30-Mar-01	30-Mar-01	20-Mar-01	Not aligned with business objectives	ISL83385EIB	J.Alcorn	(321) 724-7046
28-Mar-01	ISL83385IB-T	30-Mar-01	30-Mar-01	20-Mar-01	Not aligned with business objectives	ISL83385EIB-T	J.Alcorn	(321) 724-7046
28-Mar-01	ISL83385CA	30-Mar-01	30-Mar-01	20-Mar-01	Not aligned with business objectives	ISL83385ECA	J.Alcorn	(321) 724-7046
28-Mar-01	ISL83385CA-T	30-Mar-01	30-Mar-01	20-Mar-01	Not aligned with business objectives	ISL83385ECA-T	J.Alcorn	(321) 724-7046
28-Mar-01	ISL83385CB	30-Mar-01	30-Mar-01	20-Mar-01	Not aligned with business objectives	ISL83385ECB	J.Alcorn	(321) 724-7046
28-Mar-01	ISL83385CB-T	30-Mar-01	30-Mar-01	20-Mar-01	Not aligned with business objectives	ISL83385ECB-T	J.Alcorn	(321) 724-7046
28-Mar-01	ICL3245ECI-T	30-Mar-01	30-Mar-01	30-Mar-01	Nomenclature Change	ICL3245EIV-T	J.Alcorn	(321) 724-7046

Report 3

Distribution Date: March 30, 2001

Intersil Corporation Q1, CY2001 Quarterly Withdrawal Notice

PCN#01001

Sheet 3 of 3

Date Changes to existing Products in Withdrawal

Date	Part Type	NEW WD	NEW OBS	NEW Pre-Not	Reason	Contact	Contact Phone No.
06-Mar-01	ICL8013BCTX	30-Mar-01	29-Jun-01	No Change	No Die Available for New Builds	K.Shafer	(321) 724-7651
06-Mar-01	ICL8013CCTX	30-Mar-01	29-Jun-01	No Change	No Die Available for New Builds	K.Shafer	(321) 724-7651
12-Mar-01	CA30393	30-Mar-01	29-Jun-01	No Change	Discontinued manufacturing process	K.Shafer	(321) 724-7651
20-Mar-01	HCS20KMSR	No Change	25-May-01	No Change	Support existing order board	D.Timmerman	(321) 724-7430
28-Mar-01	CD4071BKMSRS9000	No Change	25-May-01	No Change	Pending Orders	D.Timmerman	(321) 724-7430